



D.A.V. PUBLIC SCHOOL

(Recognised by the Govt. of A.P.)

Dr. N.T.T.P.S. CAMPUS, IBRAHIMPATNAM, N.T.R. DIST. - 521 456, A.P.

E-mail : davibm1987@gmail.com | Website : davdrnttpsibm.in

Cell : 8500683223, 9441119466

Ref: DAV/IBM/2025-26/CBSE/AFF/1

Date: 18.12.2025.

To
The Concern Officer,
Affiliation Unit CBSE
Preet Vihar, Delhi – 110092.

Subject: Clarification and compliance regarding Point No. 1 – Presence of transformer and HT/LT electrical poles – reg.

Ref: 1. Application No. WL-00027-2627 dated 16/06/2025

2. Rejection Letter No. CBSE/AFF/WL-00027-2627/2026-27 dated 26/11/2025

Respected Sir/Madam,

With due respect, this is in reference to Point No. 1 mentioned in the rejection letter cited above, regarding the presence of transformer and HT/LT electrical poles in the school premises, which may pose a safety hazard. In this connection, we respectfully submit the following clarification for your kind consideration:

1. Transformer Location:

The transformer is not located inside the school premises. It is situated outside the school compound wall, at a distance of approximately 80 meters from the school main building and 60 meters from the main gate. Hence, the transformer does not fall within the school campus area.

2. Electrical Poles:

It is submitted that only Two (2) electrical poles are situated inside the school compound wall, very close to the boundary wall, and not in the student activity or academic areas.

3. Action Taken:

The school management has already submitted a written request to the concerned Electrical Department requesting the shifting of the said electrical poles outside the school compound wall in the interest of safety and compliance.


4. Alternate Safety Measure (if shifting is not feasible):

In the event that shifting of the electrical poles is not technically feasible, the school management is fully prepared to construct a new compound wall, leaving the electrical poles outside the school premises, thereby ensuring complete compliance with CBSE safety norms.

The school management is fully committed to maintaining all safety standards prescribed by CBSE and assures the Board that necessary corrective measures are being taken on priority.

We humbly request the Hon'ble Board to kindly consider the above clarification and action taken, and to allow us an opportunity for review.

Thanking you.
Yours faithfully,


18.12.25

MANAGED BY DAV COLLEGE MANAGING COMMITTEE, CHITRAGUPTA ROAD, NEW DELHI.
D.A.V. PUBLIC SCHOOL
Registration No. WL-00027-2627
Dr. N.T.T.P.S. CAMPUS
IBRAHIMPATNAM-521456



Scanned with OKEN Scanner

ANDHRA PRADESH POWER GENERATION CORPORATION LIMITED

From:
The Chief Engineer,
Operation and Maintenance,
Dr.NTTPS,
Ibrahimpatnam – 521 456,

To:
The Principal,
DAV Public School
Dr.NTTPS Campus

Memo. No. CE/O&M/Dr.NTTPS/Dy.Sec/Sr.Asst/F.no./D.No. 125 /2025, Dt: 21.12.2025

Sir,

Sub: APGENCO-Dr.NTTPS-DAV Public School-Dr.NTTPS Campus-CBSE Objection Point
No.1-Transformer and Electrical Poles -Compliance- Reg.

Ref: 1. CBSE/AFF/WL-00027-2627/2026-27,Dated:26.11.2025.
2. DAV/IBM/2025-2026/CBSE/2, Dated:17.12.2025.

In the reference cited , Sri D. Manmohan, Principal, DAV Public School, Dr.NTTPS Campus, Ibrahimpatnam, has informed regarding CBSE objection Point No.1 pertaining to the presence of transformer and electrical poles near the school premises.

In this regard, it is clarified that the transformer is not located inside the school campus and is situated outside the compound wall. However, three electrical poles are presently existing inside the compound wall.

As a part of safety compliance and in adherence to CBSE norms, the school management has already submitted a request letter to the concerned electricity authorities for shifting the said electrical poles and transformer to a faraway location from the school premises.

In case of any delay or constraints from the concerned department in shifting the electrical installations, the management hereby assures that a new compound wall will be constructed in such a manner that all electrical poles and the transformer remain completely outside the school campus, thereby ensuring maximum safety and security of the students and staff, strictly in accordance with CBSE safety guidelines.

This is submitted for information and compliance.

Chief Engineer/O&M
Dr.NTTPS/Ibrahimpatnam

Chairman L.M.C
D.A.V. PUBLIC SCHOOL
Dr. N.T.T.P.S., IBRAHIMPATNAM
Krishna (D.T.) A.P. 521456

Copy to the Superintending Engineer/Civil/Environment/Dr.NTTPS.





D.A.V. PUBLIC SCHOOL

(Recognised by the Govt. of A.P.)

Dr. N.T.T.P.S. CAMPUS, IBRAHIMPATNAM, N.T.R. DIST. - 521 456, A.P.

E-mail : davibm1987@gmail.com | Website : davdrnttpsibm.in

Cell : 8500683223, 9441119466

Ref: DAV/IBM/2025-26/CBSE/1

Date: 02.12.2025.

To
The Chief Engineer (O&M)
Dr. N.T.T.P.S Ibrahimpatnam
Vijayawada.

o/c

Subject: Request for Shifting of Transformer and Electrical Poles Near the School Campus-Reg.

Respected Sir,

I bring to your kind notice that the school has recently received a rejection letter from the CBSE stating that the presence of a high-voltage transformer and electrical poles with HT/LT lines near the school campus poses safety hazards to students. As per their remarks, these installations are considered to be within or too close to the school premises, thereby violating safety norms required for CBSE affiliation.

The school has been putting maximum efforts for the past one year to convert the institution from State Board to CBSE. After the inspection and submission of all clarifications to the CBSE authorities, the proposal for affiliation to the Secondary Level has been rejected solely due to the above-mentioned transformer and electrical poles located close to the campus.


In this connection, I humbly request your kind intervention to take necessary steps and issue instructions to the concerned authorities for shifting these electrical installations. The transformer, though situated outside the compound wall, may kindly be shifted further towards the corner of the premises for compliance with safety standards. The electrical poles, which are presently inside the compound wall, need to be relocated outside the school boundary at the earliest.

Your cooperation in resolving this issue will greatly support the school in reapplying for CBSE affiliation and ensuring a safe environment for our students.

Thank you, Sir, for your continuous support and guidance.

With regards,

Yours faithfully,


2-12-25

(D. MANMOHAN)
HEAD MASTER
D.A.V. PUBLIC SCHOOL
Dr. N.T.T.P.S. CAMPUS
IBRAHIMPATNAM-521456

MANAGED BY DAV COLLEGE MANAGING COMMITTEE, CHITRAGUPTA ROAD, NEW DELHI.



Scanned with OKEN Scanner



D.A.V. PUBLIC SCHOOL

(Recognised by the Govt. of A.P.)

Dr. N.T.T.P.S. CAMPUS, IBRAHIMPATNAM, N.T.R. DIST. - 521 456, A.P.

E-mail : davibm1987@gmail.com | Website : davdrnttpsibm.in

Cell : 8500683223, 9441119466

Ref: DAV/IBM/2025-26/CBSE/02

Date: 13.12.2025

To
The Assistant Executive Engineer
Electrical Department
Kondapalli
Krishna District, Andhra Pradesh

O/C

Subject: Request for shifting of electrical transformer and poles from school campus – Reg.

Respected Sir/Madam,

With due respect, we wish to bring to your kind notice that D.A.V Public School, Kondapalli, has been functioning in Kondapalli village for the last 40 years, under the administrative control of APGENCO. Recently, the school applied for CBSE affiliation by upgrading from the State Board.

During the CBSE inspection process, it was observed and strongly objected that an electrical transformer is located outside in the middle of the school compound wall, and electrical poles belonging to the Electrical Department are situated inside the school premises. The CBSE inspection committee has clearly mentioned that the presence of these electrical installations poses a serious safety hazard to students and staff, and hence the school's application for CBSE affiliation has been rejected under Finding No. 1.


In this connection, we humbly request your good office to kindly shift the electrical transformer from the middle of the compound wall to the corner of the compound wall, and also relocate the electrical poles outside the school campus, at the earliest possible time. This will ensure the safety of students and help the school comply with CBSE safety norms and infrastructure requirements.

The school is keen to clear the CBSE objection and obtain CBSE affiliation at the earliest, as it is in the best academic interest of students belonging to this rural and socio-economically weaker section.

We sincerely hope for your kind cooperation and immediate action in this matter.

Thanking you in anticipation.

Yours sincerely,



13-12-25

Principal

HEAD MASTER
D.A.V. PUBLIC SCHOOL
D.A.V. Public School, Kondapalli
Dr. N.T.T.P.S. CAMPUS
IBRAHIMPATNAM 521456

MANAGED BY - DAV COLLEGE MANAGING COMMITTEE, CHITRAGUPTA ROAD, NEW DELHI.





D.A.V. PUBLIC SCHOOL

(Recognised by the Govt. of A.P.)

Dr. N.T.T.P.S. CAMPUS, IBRAHIMPATNAM, N.T.R. DIST. - 521 456, A.P.

E-mail : davibm1987@gmail.com | Website : davdrnttpsibm.in

Cell : 8500683223, 9441119466

Ref: DAV/IBM/2025-26/01

Date: 12.12.2025

To
The Municipal Commissioner
Kondapalli Municipality
Kondapalli, Andhra Pradesh.

ok

Subject: Request for Removal/Relocation of Electrical Transformer and Poles from School Campus-Reg.

Respected Sir,

We, the Management of D.A.V Public School, Kondapalli, have been serving the children of Kondapalli village for the past 40 years under APGENCO (Thermal Power Station). Recently, our school has applied for CBSE affiliation, transitioning from the State Board to CBSE.

During the CBSE inspection process, it was observed that an electrical transformer and several electrical poles are located inside the school campus. The CBSE inspection team has raised a major safety objection, stating that the presence of a transformer within the school premises poses a serious hazard to students and staff. This issue has become a barrier to obtaining CBSE affiliation.

In this connection, we earnestly request your support and intervention. We kindly request you to recommend and direct the concerned electricity authorities to relocate the transformer and electrical poles from the school campus at the earliest. This relocation is essential for ensuring student safety and for enabling us to proceed with the CBSE affiliation.

Your timely action in this matter will greatly help us in providing a safer educational environment and in improving the academic standards of the children of Kondapalli.

We shall be grateful for your kind support and early action.

Thanking you,

Yours sincerely

PHENIL MASTER

D.A.V. PUBLIC SCHOOL

MANAGED BY DAV COLLEGE MANAGING COMMITTEE, CHITRAGUPTA ROAD, NEW DELHI.

IBRAHIMPATNAM-521456





22 Dec 2025



motorola edge 60 pro

D. A. V. SCHOOL VIJAYAWADA



motorola edge 60 pro
D.A.V SCHOOL VILAYAWADA

23 Dec 2025