

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From
Yeeda Seshibhushan
Deputy Executive Engineer,
(R & B) Sub-Division.
Vijayawada.

To
The Principal,
D.A.V. Public School,
Dr. N.T.T.P.S. Campus,
Ibrahimpattam,
N.T.R. District-521 456.

Lr.No. DEE/VJA/ Soundness Certificate/2026-2027/ **Date:01.05.2026**


Sir,

Sub: – (R&B) Sub- Division, Vijayawada – Soundness Certificate for D.A.V. Public School, Dr.N.T.T.P.S. Campus, Ibrahimpattam, NTR District – 521 456 – Reg.

Ref: – 1) Representation of the Principal D.A.V. Public School, Dr.N.T.T.P.S. Campus, Ibrahimpattam, NTR District.

I enclose herewith the structural soundness certificate to D.A.V. Public School, Dr.N.T.T.P.S. Campus, Ibrahimpattam, NTR District valid for the period from 01.05.2026 to 30.04.2027 (One year) and same is herewith enclosed.

Yours sincerely,


Deputy Executive Engineer(R&B)
(R&B) Sub-Division, Vijayawada

Encl: Soundness Certificates

SOUNDNESS CERTIFICATE

1	Address of the School/College	:	D.A.V. Public School, Dr. N.T.T.P.S., Campus, Ibrahimpatnam, NTR District – 521456
2	College/School Running in	:	RCC Building
3	No. of Floors	:	G+1
4	Stilt Floor/Ground Floor used as	:	Class Rooms
5	Constructed in the year	:	1986
6	Constructed as per approved plan	:	Yes
7	Present period up to which certificate is in force	:	NA
8	Any cracks developed in the walls in superstructure and basement	:	Nil
9	Condition of lintels and walls above the lintel	:	Satisfactory
10	Condition of beams and the Trusses	:	Satisfactory
11	Development of Cracks	:	Nil
12	Exposed reinforcement, if any	:	Nil
13	Condition of Doors and Windows	:	Satisfactory
14	The width of the staircase flight is	:	1.25 m against required minimum of 1.50 m
15	Tread width is	:	0.24 m against required minimum of 0.30 m
16	The height of rise	:	0.14 m against maximum of 0.15 m
17	The height of railing	:	0.90 m against required minimum of 1.20 m
18	The height of Corridor parapet wall	:	2.32 m & 0.78 m
19	Doorway dimensions	:	Width is 1.18 m against required minimum of 1.00 m & 2.25 height against 2.00 m
20	Height of Parapet wall	:	0.78 m
21	Internal corridor width	:	2.40 m
22	Any Cantilever corridors	:	NA
23	Number of exits	:	2 Nos
24	There is high tension electricity lines passing near to the building	:	No

25	There is Petrol/Gas stations near to the building	:	No
26	Grills are provided for all sides of balconies as children safety point of view	:	Yes
27	Building plan submitted	:	Yes
28	Building Foundation and Structural design submitted	:	No
29	Building was last painted in the year	:	2023

The management is advised to attend the short falls identified in the above items and submit the details in this office. Otherwise, soundness Certificate will not be renewed by the department.

However, the building is safe for a period of One Year i.e., from 01.05.2026 to 30.04.2027

[Signature]
Deputy Executive Engineer(R&B)
(R&B) Sub-Division, Vijayawada